

Market Release Note

MRN-TS91016-V10-06-R4

Product number: TS1016, TS1016B, TS1016SE, TS1016SEB

Product description: Challenger10, ChallengerSE

Product version: V10-06-9746

Affected parts: n/a

Release date: 19th May 2016

Resolved Issues

- Users not uploading to software correctly when IUM is fitted
- CPU restart messages appear in certain conditions
- Start / End dates for users not being stored in panel in certain conditions
- After defaulting the panel, history log would show alarms on Input 0
- Tweaks for 3G Comms Module authentication options
- Opens / Closes not triggering dialler in certain conditions
- Dialler not being triggered if events occur within wait time between connections
- Deleting all Timezones not being passed on to intelligent controllers
- Timezones 42-63 not being sent to 4DC
- Various spelling and interface fixes

Known issues

- Any Challenger10 or ChallengerSE panel upgrading from a version of firmware older than V10-06 will be classed as a new panel type when updated to this firmware. This means that the panel record will need to be converted to the new type in the software (Security Commander, Titan, Forcefield). Please refer to the manuals or call support if further information is required.
- Non-polled peripherals are not backed up or restored when using the SD card.

Documentation and Downloads

Marketing Collateral	Challenger10 datasheet
	ChallengerSE datasheet
	Challenger overview
	Tecom Hardware Matrix
Technical Manuals	Challenger Series Programming Manual *
	Challenger Series Users Manual
	Challenger Series Administrators Manual
	Challenger Series Installation and Quick Programming Manual
Firmware Download	Firmware V10-06-9746 (SREC)
	Firmware V10-06-9746 (ZIP)

- Requires login at Interlogix Support Portal

All downloads can be found at www.interlogix.com.au/downloads