

Market Release Note

MRN-TS9100-72B45

Product number: TS9100, TS9120

Product description: Forcefield

Product version: TS9100 7.2 Build 45

Release date: 10 November 2015

Interlogix is pleased to announce the immediate availability of Forcefield 7.2

New features

Forcefield 7.2 offers the following improvements:

- Support for new features in Challenger10 V10-06 firmware. Major enhancements include:
 - Device descriptions stored in the panel
 - Automation Zones (configuration only)
 - 3G Communication Module
 - See Challenger V10-06 MRN for full list of changes in new firmware
- Support for 3G connection to Challenger10, ChallengerSE and ChallengerLE panels fitted with 3G Communication Module
- Support for the new ChallengerLE panel
- New functionality to help with system management
 - New form to display live status of Challenger communications
 - Printer detail status form now updates dynamically
 - New report status form displays the number of reports running and details of the reports (provided the member credentials of the current operator match the report credentials)
 - New form to synchronise panel time to Forcefield time, by selected panels (does not apply to dialler panels)

- User interface enhancements
 - Added “Select all of page” and “Clear all on page” option for bulk selecting check boxes on Search and Select screens.
 - Added buttons to find first, next, previous and last checked items in Search and Select screens.
 - Changes IP address fields, so they are single field (instead of four) to make data entry easier.

- Performance and stability enhancements
 - New Challenger download manager. Total number of concurrent download processes can be configured. Panels can be assigned download priorities.
 - History server now enforces a maximum of 3,500,000 records (in live history), regardless of configuration.
 - Option has been added to delete oldest record in history instead of initiating a purge.
 - Mount Server enhanced to “tickle” SMB connections in attempt to prevent network equipment closing the SMB ports due to no activity.
 - Increased tolerance for low memory detection for watchdog process to avoid premature shutdown of node.
 - Details of memory usage now included in low memory and low disk space events.

Documentation

Marketing Collateral	Forcefield datasheet
	Tecom software comparison matrix
	TruVision video plugin datasheet
	Genetec video plugin datasheet
Technical Manuals	Forcefield Installation and Setup Manual
	Forcefield Operators Manual
	Forcefield External Interfaces Manual
	Forcefield Licence Form

Visit www.interlogix.com.au/downloads
to download the latest software and firmware versions.

Issues resolved in this release

- Printer drivers attempt to reconnect with the print spooler if connection becomes lost. Previously printing stopped forever.
- Resolved occasional lock-up issues with Time Server
- Resolved occasional Database Manager crashes
- User Activity from map icon now accurately shows “No Activity” if there has been no user activity.
- Recall server now handles door forced, DOTL and open/close statuses properly.
- Changing user dates via bulk modify now downloads user details to panels if necessary.
- Challenger download doesn't report “Physical D/L Start” if no records are found in download buffer.
- Resolved intermittent connectivity issues with Teleste by fixing buffer sizes for hash and license keys.

Known issues

- Serial printing to a third party system sometimes stops working when the system is under heavy load. As a result, occasionally the server will need to be restarted to resume functionality.