

Market Release Note

MRN-TS97101-23B5

Product number: TS97101

Product description: Security Commander 2.3

Product version: TS97101 2.3 Build 5

Release date: 15th October 2015

Interlogix is pleased to announce the immediate availability of Security Commander 2.3.

New features

Security Commander 2.3 offers the following improvements:

- Support for Windows 10 Pro and above (64-bit)
- Support for the new ChallengerLE panel
- Person form improvements
 - Person form can now be filtered based on last user access. E.g. an operator can now only show persons that have not been active for the last thirty days. Those person records can now be easily bulk modified or deleted.
 - Person records can now be deleted while badge records are assigned to them

Documentation

Marketing Collateral	Security Commander datasheet
	Tecom software comparison matrix
	Tecom (Security Commander) A&E Specification
	TruVision video plugin datasheet
	Genetec video plugin datasheet
Technical Manuals	Security Commander Administrators Manual and Operation Guide
	Security Commander Installation Manual
	Security Commander API Installation and Operation Manual
	Security Commander CCTV Interface Guide
	Security Commander SQL Server Mirroring Guide
	Security Commander Photo ID User Guide
Software download	Security Commander 2.3, build 5

Issues resolved in this release

- Changed maximum live history and badge monitor records from 10,000 to 1,000 to improve performance.
- Lift cars can now be configured with full range of values
- Improved panel reliability of panel communications
- The first assigned badge record on the person form is now highlighted by default. This means badge option controls on the person form are enabled by default.
- Facility filtering on “Person in Group” reports now works correctly.
- Facility filtering on History reports is now based on Person Facility, to enable more relevant results.
- Monitor forms are no longer squashed when opened in their default position. They now open on the right hand side of the user interface.
- An individual monitor form position is now saved when the form is closed (previously they only saved when the operator logged out of the software)
- The drop-down Person filter list in the History report now orders items correctly so the filter by <ALL> will always work correctly.
- The “Time to trigger” field in the RAS and Door forms no longer delete their values as soon as it is saved.

- The “Time to trigger” field in the RAS and Door forms is no longer mandatory.
- Email triggering now works more reliably
- The bottom of the control form is no longer cut-off
- Door/floor/alarm groups assigned to a person, which an operator could not see due to Facility restrictions are no longer deleted when a restricted operator edits the person’s groups.

Known issues

- Activation codes from older versions of Security Commander (2.1 and earlier) will not work with Security Commander 2.2 or 2.3. This is because the encoding of the activation code needed to be changed. Customers who have an existing code are still eligible to upgrade to Security Commander free of charge. However, they will need to call Interlogix to obtain an updated activation code.
- On rare occasions, the photo ID module will produce errors with Windows 8 installations.